

FOREVER GmbH Robert-Bosch-Str. 43, 68542 Heddesheim, Germany **Phone:** +49 (0) 62 03/930 20 - 0 **Fax:** +49 (0) 62 03/930 20 - 40

E-mail: info@forever-ots.com **Web:** www.forever-ots.com

Transfer Instructions for:

FOREVER Subli-Light for SUBLIMATION SURFACES



PRINT SETTINGS:

• Only for use in Ink-Jet Printers with Sublimation Inks!

• Image Mode: Mirror Image



TRANSFER SETTINGS:

MATERIAL	(°C)	TIME	PRESSURE
POLYESTER	200°C (392°F)	45-55 Sec.	medium
TOTE BAG	200°C (392°F)	45-55 Sec.	medium
BANNER FABRICS	200°C (392°F)	60 Sec.	medium
PLAQUES	200°C (392°F)	75 Sec.	medium
MOUSE PAD	200°C (392°F)	60-75 Sec.	medium
GLASS	200°C (392°F)	8 Min.	medium-maximal
METAL	200°C (392°F)	75 Sec.	medium
MUGS	180°C (356°F)	45 Sec.	medium



TRANSFER APPLICATION:

- Print the design with an Ink-Jet Printer with Sublimation Inks.
- Place the FOREVER Subli-Light onto the garment.
- Press it according the table above.



Before starting a mass production, we recommend to make transfer and washing test with all materials.



Important advice for double-sided printing on textiles:

T-Shirts for a **double-sided print** (frontside & backside), has to be put over the lower heat plate. In this case only one side will be treated with heat and you avoid that the applicated design from the other side will be pressed out again.